

ACCÉLÉROMÈTRES

| Capteur # | Type | Accélération |
|------------------|---------------------|---------------------|
| 3B13470 | IC Sensors 3140-002 | ±2 g |
| 3B13473 | IC Sensors 3140-002 | ±2 g |
| 0596-003 | IC Sensors 3140-002 | ±2 g |
| 0596-004 | IC Sensors 3140-002 | ±2 g |
| 3497-014 | IC Sensors 3140-002 | ±2 g |
| 3497-017 | IC Sensors 3140-002 | ±2 g |
| 3497-049 | IC Sensors 3140-002 | ±2 g |
| 3523-003 | IC Sensors 3140-005 | ±5 g |
| 3523-004 | IC Sensors 3140-005 | ±5 g |
| 3523-006 | IC Sensors 3140-005 | ±5 g |
| 3521-041 | IC Sensors 3140-005 | ±5 g |
| 3B13370 | IC Sensors 3140-010 | ±10 g |
| 3B13390 | IC Sensors 3140-010 | ±10 g |
| 3B10864 | IC Sensors 3140-050 | ±50 g |
| 3B11161 | IC Sensors 3140-050 | ±50 g |